



OWENS-CORNING FIBERGLAS CORPORATION

FIBERGLAS TOWER, TOLEDO, OHIO 43659, (419) 248-8000

March 22, 1982

U.S. Environmental Protection Agency
Sites Notification - Region X
1200 Sixth Ave.
Seattle, WA 98101

Subject: CERCLA NOTIFICATIONS

Gentlemen:

It has come to our attention that the sites which were reported last June under "Superfund" are now being reviewed at the regional offices and state agencies for priority. We have reviewed our submissions based on development of regulatory definition of "hazardous waste" since June 1981 and find some cases of facilities which were reported then, but would not be reportable now.

Such a case would appear to be our report of the wastewater treatment facility at our plant at St. Helens, Oregon (copy attached).

This was notified because small amounts of chemicals entered the wastewater. Under the rationale of the November 17, 1981 revision to 261.3, this does not make it a hazardous waste facility. No accumulation of hazardous waste is located here, and you may be able to eliminate it from further consideration.

Sincerely,

C. A. Harrison, Manager
Solid Waste and Hazardous Waste

attach.

cc: Superfund Site Notification
Dept. of Environmental Quality
522 S.W. 5th Ave.
Portland, Oregon 97207

RECEIVED
MAR 25 1982

PROGRAM DEVELOPMENT SECTION

USEPA SF



1443763



Notification of Hazardous Waste Site

United States
Environmental Protection
Agency
Washington DC 20460

This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must be mailed by June 9, 1981.

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies

Pub. Aff. 82

A Person Required to Notify:

Enter the name and address of the person or organization required to notify.

Name Owens-Corning Fiberglas Corporation
Street Fiberglas Tower
City Toledo State Ohio Zip Code 43659

B Site Location:

Enter the common name (if known) and actual location of the site

Name of Site Owens-Corning Fiberglas Corporation
Street Old Portland Road
City St. Helens County _____ State OR Zip Code 97051

C Person to Contact:

Enter the name, title (if applicable), and business telephone number of the person to contact regarding information submitted on this form.

Name (Last, First and Title) William L. Kreutz, Esquire
Phone (419) 248-8220

D Dates of Waste Handling:

Enter the years that you estimate waste treatment, storage, or disposal began and ended at the site.

From (Year) 1930 To (Year) Present

E Waste Type: Choose the option you prefer to complete

Option 1: Select general waste types and source categories. If you do not know the general waste types or sources, you are encouraged to describe the site in Item I—Description of Site.

General Type of Waste:

Place an X in the appropriate boxes. The categories listed overlap. Check each applicable category.

- 1. ☐ Organics
- 2. ☐ Inorganics
- 3. ☐ Solvents
- 4. ☐ Pesticides
- 5. ☐ Heavy metals
- 6. ☐ Acids
- 7. ☐ Bases
- 8. ☐ PCBs
- 9. ☐ Mixed Municipal Waste
- 10. ☒ Unknown
- 11. ☐ Other (Specify)

Source of Waste:

Place an X in the appropriate boxes.

- 1. ☐ Mining
- 2. ☐ Construction
- 3. ☐ Textiles
- 4. ☐ Fertilizer
- 5. ☐ Paper/Printing
- 6. ☐ Leather Tanning
- 7. ☐ Iron/Steel Foundry
- 8. ☐ Chemical, General
- 9. ☐ Plating/Polishing
- 10. ☐ Military/Ammunition
- 11. ☐ Electrical Conductors
- 12. ☐ Transformers
- 13. ☐ Utility Companies
- 14. ☐ Sanitary/Refuse
- 15. ☐ Photofinish
- 16. ☐ Lab/Hospital
- 17. ☐ Unknown
- 18. ☒ Other (Specify)
Mfg. Wood Fiber
Products

Option 2: This option is available to persons familiar with the Resource Conservation and Recovery Act (RCRA) Section 3001 regulations (40 CFR Part 261).

Specific Type of Waste:

EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter the appropriate four-digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the site is located.

F Waste Quantity:

Place an X in the appropriate boxes to indicate the facility types found at the site.

In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons.

In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.

Facility Type

1. ☐ Piles
2. ☐ Land Treatment
3. ☐ Landfill
4. ☐ Tanks
5. ☐ Impoundment
6. ☐ Underground Injection
7. ☐ Drums, Above Ground
8. ☐ Drums, Below Ground
- 9 ☒ Other (Specify) Wastewater Treatment

Total Facility Waste Amount

cubic feet See site description below (Section I)

gallons _____

Total Facility Area

square feet _____

acres See site description below (Section I)

G Known, Suspected or Likely Releases to the Environment:

Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment.

☐ Known ☐ Suspected ☒ Likely ☐ None

Note: Items Hand I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

H Sketch Map of Site Location: (Optional)

Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.

I Description of Site: (Optional)

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

Information on the hazardous waste activity at the St. Helens Plant is quite sketchy. There were apparently small amounts of various chemical materials which have been used at the Plant over the years that may have entered the water systems through the fabrication process or intentional discharge. The wastewater treatment operation would then process the water

for eventual reuse as process make-up water or it would be discharged to the Scappose Bay where it is regulated by an N.P.D.E.S. permit. Sludge from the lagoon has been disposed of within the approval of the Oregon Department of Environmental Quality.

J Signature and Title:

The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the

Name William L. Kreutz, Esquire

Owens-Corning Fiberglas Corporation

Street Fiberglas Tower

City Toledo

State Ohio Zip Code 43659

- ☒ Owner, Present
☐ Owner, Past
☐ Transporter
☒ Operator, Present
☐ Operator, Past
☐ Other



cc: Mike Basell
9/23/81

OWENS-CORNING FIBERGLAS CORPORATION

FIBERGLAS TOWER, TOLEDO, OHIO 43659, (419) 248-8000

September 17, 1981

Mr. Bob Stammes, Engineer
U. S. Environmental Protection Agency
M/S 534
1200 6th Avenue
Seattle, Washington 98101

Re: Superfund Notification
St. Helens Plant

Dear Mr. Stammes:

Confirming our telephone conversation this date, I am enclosing correspondence between Owens-Corning and Oregon D.E.Q. with regard to disposal of waste treatment sludge. Mr. Harrison's October 31, 1980 letter to Mr. Gray contains a detailed analysis of the sludge. Mr. Gray's response of November 10, 1980 confirms to the disposal site operator that the sludge is similar to pulp fiber solids.

Should you have any further questions, please contact me.

Very truly yours,

Thomas R. Merlino
Legal Counsel
(419) 248-8221

TRM:dep

Enclosures

RECEIVED
SEP 21 1981

TECHNICAL OPERATIONS SECTION

LETTER TO SANTOSH DISPOSAL
APPROVING SLUDGE DISPOSAL

Department of Environmental Quality

522 SOUTHWEST 5TH AVE. PORTLAND, OREGON

MAILING ADDRESS: P.O. BOX 1760, PORTLAND, OREGON 97207

DR ATIYEH
VERNOR

November 10, 1980

Mr. Phil Holsheimer, Jr.
Santosh Disposal Corporated
Rt. 1 Box 132
Scappoose, OR 97056


Re: SW-Columbia County
Santosh Disposal Site
SWP No. 195

Dear Mr. Holsheimer, Jr.

This will confirm the authorization given to you on November 4, 1980, regarding disposal of approximately 400,000 gallons of dredge solids from Owens Corning Fiber-glass Corporation, St. Helens, Oregon. The material will be coming from Owens Corning Fiber-glass Corporation's waste treatment ponds.

The material is similar to pulp fiber solids which you receive on a routine basis. If you should need any additional information please feel free to contact me at 229-5288.

Sincerely,



Charles H. Gray
Assistant Regional Manager
Northwest Region

CHG:f

RFD146 (2)

cc: Solid Waste Management, DEQ
Bruce Paskett, Owens Corning

RECEIVED

NOV 13 1980

OWENS/CORNING FIBERGLAS CORP.
ST. HELENS, OREGON